


TRE'R CEIRI
CONSERVATION PROJECT
1989 - 90
PART 2: PLATES



Ymddiriedolaeth Archaeolegol Gwynedd Cyf
Gwynedd Archaeological Trust Ltd

REPORT ON THE FIRST SEASON OF THE
TRE'R CEIRI CONSERVATION PROJECT
DECEMBER 1989 - MARCH 1990

S.D. BOYLE

FOR

GWYNEDD ARCHAEOLOGICAL TRUST LTD.

PART 2: PLATES

List of Plates.

(Negative nos. are given in brackets next to each plate).

1. Hut 86 before conservation.
2. Hut 86: blocked entrance.
3. Hut 86: E corner, before conservation.
4. Hut 86: NE wall after clearance of tumbled stones.
5. Hut 86: NE wall and entrance restored.
6. Hut 86: outer face of NE wall before conservation.
7. Hut 86: outer face of NE wall after clearance of tumble.
8. Hut 86 after conservation.
9. Hut 86 before conservation.
10. Hut 86 after conservation.
11. Hut 51 before conservation.
12. Hut 51 before conservation.
13. Hut 51 before conservation.
14. Hut 51, N corner: facing stones revealed.
15. Hut 52 before conservation.
16. Hut 52: E wall before conservation.
17. Hut 52: refacing SE corner of hut.
18. Hut 52: E wall after conservation.
19. Hut 72 before conservation.
20. Hut 72: NE wall before conservation.
21. Hut 72: NE wall before conservation.
22. Hut 72: NE wall after conservation.
23. Hut 72: NE wall after conservation.
24. Hut 72: SE wall before conservation.
25. Hut 72: remains of partition uncovered.
26. Hut 72: rebuilding the partition.
27. Hut 72 after conservation.
28. Hut 92 before conservation.
29. Hut 92: SE wall before conservation.
30. Hut 92: SE wall during conservation.
31. Hut 92: SE wall after conservation.
32. Wall between huts 72 and 92 before conservation.
33. Wall between huts 72 & 92 after conservation.
34. Wall between huts 72 & 92 after conservation.
35. Hut 92: NW wall before conservation.
36. Hut 92: NW wall after conservation.
37. Hut 92: E entrance before conservation.
38. Hut 92: rubble removed from E entrance.
39. Hut 92: inner end of E entrance, after removal of rubble.
40. Hut 92: E entrance after conservation.
41. Hut 92: possible N entrance before conservation.
42. Wall between huts 92 & 73 before conservation.
43. Hut 92: rubble cleared from possible N entrance.
44. Hut 92: possible N entrance after conservation.
45. Hut 73 before conservation.
46. W end of hut 73 before conservation.
47. E end of hut 73 before conservation.
48. Hut 73: E wall, tumble removed.
49. Hut 73: E wall, tumble removed.
50. Hut 73: E wall, tumble removed, with W corner of hut 74 exposed.

51. NE corner of hut 73 and W corner of hut 74.
52. Hut 73: E wall rebuilt.
53. Hut 73: NW entrance re-opened.
54. Hut 36: NE wall before conservation.
55. Hut 36: interior and NW wall before conservation.
56. Hut 36: blocked entrance.
57. Wall between huts 36 & 87.
58. Hut 36: entrance cleared.
59. Hut 87: NE wall before conservation.
60. Hut 87: SW wall before conservation.
61. Hut 87: interior and W corner before conservation.
62. Hut 87: interior and E corner before conservation.
63. Hut 87: outer face of S wall before conservation.
64. Hut 87: NE wall after removal of tumble.
65. Hut 87: core removed at E corner, exposing outer face of hut 53.
66. Hut 87: NE wall after conservation.
67. Hut 87: SE corner after removal of collapse, with original outer face of hut 53 exposed.
68. Hut 87: E and S walls after conservation.
69. Hut 87 and W wall of hut 53 after conservation.
70. Hut 87 after conservation.
71. Hut 89: N wall before conservation.
72. Hut 53: interior and W wall before conservation.
73. Hut 90: SE wall before conservation.
74. Huts 89 & 90: E and NE walls before conservation.
75. Hut 90: E wall before conservation.
76. Huts 89 & 90: internal partition before conservation.
77. Hut 90: entrance from hut 53 before conservation.
78. Hut 89: entrance from hut 53 before conservation.
79. Hut 90: entrance from hut 53 in 1956.
80. Hut 89: entrance from hut 53 in 1956.
81. Hut 53: inner face of W wall after removal of tumble.
82. Hut 53: foundations of W jamb of doorway to hut 89.
83. Hut 90: base of E wall after removal of collapse.
84. Hut 89: base of NE wall after removal of collapse.
85. Hut 89: foundations of possible cross wall.
86. Hut 89: restored N and NE walls.
87. Hut 90: restored E wall.
88. Huts 89 & 90: restored NE wall.
89. Hut 89: NW wall before conservation.
90. Hut 89: NW wall after conservation.
91. Hut 89: general view after conservation.
92. Hut 87: NE wall with experimental capping.
93. Inner rampart, length D-E, showing changes in construction.
94. Inner rampart, length D-E, showing changes in construction.
95. N postern, outer end in 1956.
96. N postern, outer end before conservation in 1989.
97. N postern, inner end in 1956.
98. N postern, inner end before conservation in 1989.
99. N postern and 'ramp': general view before conservation.
100. N postern: access cleared in front of passage.
101. Parapet to E of N postern, looking E.
102. N postern: original inner wall face exposed to E of passage.
103. N postern: E side of passage partly cleared.

104. N postern: original inner wall face exposed to W of passage.
105. N postern: the outer lintel before removal.
106. The broken lintel.
107. N postern: outer E corner of passage before dismantling.
108. N postern: outer E corner of passage after dismantling.
109. N postern after conservation.
110. N postern: outer W corner before conservation.
111. N postern: outer W corner before conservation.
112. N postern: E face of passage during clearance.
113. N postern: E side of passage before dismantling.
114. N postern: E side of passage after dismantling, with original inner wall face exposed.
115. N postern: E side of passage after conservation.
116. N postern: W side of passage after conservation.
117. N postern, with replacement lintels.
118. N postern after re-roofing.
119. N postern after re-roofing.
120. Collapse 'N' before conservation.
121. Collapse 'N' after clearance of tumble.
122. Collapse 'N' after clearance of tumble.
123. Collapse 'N': wall being refaced.
124. Collapse 'N' after conservation.
125. Collapse 'N' after conservation.
126. Collapse 'N': top of wall after conservation, with rebuilt parapet.
127. Collapse 'N': inner face after conservation.
128. Collapse 'N': inner face after conservation.
129. Collapse 'E1' before conservation.
130. Collapse 'E1' after removal of tumble.
131. Collapse 'E1' after removal of tumble.
132. Collapse 'E1' after conservation.
133. Collapse 'E1' after conservation.
134. Outer face of rampart, with collapse 'F1' in centre, before conservation.
135. Collapse 'F1' after conservation.
136. Collapse 'F1': top of wall after conservation.



Plate 1. Hut 86 before conservation, looking SE (G1022/001/08).



Plate 2. Hut 86: blocked entrance, looking SE (G1022/001/14).



Plate 3. Hut 86: E corner, before conservation (G1022/001/13).



Plate 4. Hut 86: NE wall after clearance of tumbled stones, looking NE (G1022/005/12A).



Plate 5. Hut 86: NE wall and entrance restored, looking SE (G1022/022/04A).



Plate 6. Hut 86: outer face of NE wall before conservation, looking SE (G1022/003/15).



Plate 7. Hut 86: outer face of NE wall after clearance of tumble,
looking S (G1022/005/15A).



Plate 8. Hut 86 after conservation, looking SE (G1022/022/03A).



Plate 9. Hut 86 before conservation, looking W (G1022/001/11).



Plate 10. Hut 86 after conservation, looking W (G1022/022/06A).



Plate 11. Hut 51 before conservation, looking NE (G1022/001/19).



Plate 12. Hut 51 before conservation, looking NW (G1022/001/15).



Plate 13. Hut 51 before conservation, looking W (G1022/001/16).



Plate 14. Hut 51, N corner: facing stones revealed (G1022/005/16A).



Plate 15. Hut 52 before conservation, looking NW (G1022/001/23)



Plate 16. Hut 52: E wall before conservation, looking E (G1022/001/25).



Plate 17. Hut 52: refacing SE corner of hut, looking SE
(G1022/005/17A).



Plate 18. Hut 52: E wall after conservation, looking E (G1022/022/21A)



Plate 19. Hut 72 (left of frame) before conservation, looking W
(G1022/001/05).



Plate 20. Hut 72: NE wall before conservation, looking NE
(G1022/001/30).



Plate 21. Hut 72: NE wall before conservation,
looking SE (G1022/001/31).

Plate 22. Hut 72: NE wall
after conservation, looking
NW (G1022/022/18A).



Plate 23. Hut 72: NE wall
after conservation, looking
NE (G1022/022/19A).





Plate 24. Hut 72: SE wall before conservation,
looking SW (G1022/001/29).

Plate 25. Hut 72: remains of
partition uncovered, looking
SE (G1022/005/18A).



Plate 26. Hut 72: rebuilding
the partition, looking SW
(G1022/005/19A).





Plate 27. Hut 72 after conservation, looking NE (G1022/022/20A).



Plate 28. Hut 92 before conservation, looking SW (G1022/001/34).



Plate 29. Hut 92: SE wall before conservation, looking SE
(G1022/002/05A).



Plate 30. Hut 92: SE wall during conservation, looking SE
(G1022/005/20A).



Plate 31. Hut 92: SE wall after conservation, looking SE
(G1022/021/30).



Plate 32. Wall between huts 72 and 92 before conservation
looking SW (G1022/001/32).



Plate 33. Wall between huts
72 & 92 after conservation,
looking W (G1022/022/17A).



Plate 34. Wall between huts
72 & 92 after conservation,
looking SW (G1022/022/15A).



Plate 35. Hut 92: NW wall before conservation, looking NW
(G1022/001/36).



Plate 36. Hut 92: NW wall after conservation, looking NW
(G1022/021/33).



Plate 37. Hut 92: E entrance
before conservation, looking
E (G1022/002/06A).



Plate 38. Hut 92: rubble
removed from E entrance,
looking E (G1022/005/24A).



Plate 39. Hut 92: inner end of E entrance, after removal of rubble, looking NE (G1022/005/22A).



Plate 40. Hut 92. E entrance after conservation, looking E (G1022/021/28).



Plate 41. Hut 92: Possible N entrance before conservation, looking N (G1022/002/07A).



Plate 42. Wall between huts 92 & 73 before conservation, looking E (G1022/002/17A).



Plate 43. Hut 92: rubble cleared from possible N entrance,
looking NE (G1022/005/23A).



Plate 44. Hut 92: Possible N entrance after conservation,
looking N (G1022/022/35A).



Plate 45. Hut 73 (left of centre) before conservation,
looking NW (G1022/001/07).



Plate 46. W end of hut 73 before conservation, looking W
(G1022/002/14A).



Plate 47. E end of hut 73 before conservation, looking E
(G1022/002/12A).



Plate 48. Hut 73: E wall, tumble removed, looking E (G1022/006/02).

Plate 49. Hut 73: E wall,
tumble removed, looking SE
(G1022/006/07).



Plate 50. Hut 73: E wall,
tumble removed, with W corner
of hut 74 exposed, looking E
(G1022/006/03).



Plate 51. NE corner of hut
73 and W corner of hut 74,
looking NW (G1022/006/06).



Plate 52. Hut 73: E wall
rebuilt, looking E
(G1022/022/13A).





Plate 53. Hut 73: NW entrance re-opened, looking NW (G1022/022/14A).



Plate 54. Hut 36: NE wall before conservation, looking NE (G1022/005/08A).



Plate 55. Hut 36: interior and NW wall before conservation,
looking NW (G1022/005/09A).



Plate 56. Hut 36: blocked entrance, looking NE (G1022/005/11A).

Plate 57. Wall between huts
36 & 87, looking SW
(G1022/004/24).



Plate 58. Hut 36: entrance
cleared, looking NE
(G1022/022/12A).





Plate 59. Hut 87: NE wall
before conservation, looking
NE (G1022/004/25).



Plate 60. Hut 87: SW wall
before conservation, looking
NW (G1022/004/20).



Plate 61. Hut 87: interior and W corner before conservation,
looking W (G1022/004/18).



Plate 62. Hut 87: interior and E corner before conservation,
looking E (G1022/004/17).



Plate 63. Hut 87: outer face of S wall before conservation,
looking N (G1022/004/16).



Plate 64. Hut 87: NE wall after removal of tumble,
looking E (G1022/007/04).



Plate 65. Hut 87: core removed at E corner, exposing outer face of hut 53, looking E (G1022/015/24).



Plate 66. Hut 87: NE wall after conservation, looking NE (G1022/022/09A).



Plate 67. Hut 87: SE corner after removal of collapse, with original outer face of hut 53 exposed, looking SE (G1022/007/13).



Plate 68. Hut 87: E and S walls after conservation, looking S (G1022/022/10A).



Plate 69. Hut 87 and W wall of hut 53 after conservation,
looking W (G1022/022/11A).



Plate 70. Hut 87 after conservation, looking SE (G1022/022/07A).



Plate 71. Hut 89: N wall before conservation, looking NE
(G1022/004/07).



Plate 72. Hut 53: interior and W wall before conservation,
looking NW (G1022/003/12).



Plate 73. Hut 90: SE wall before conservation, looking SE
(G1022/003/04).



Plate 74. Huts 89 & 90: E and NE walls before conservation,
looking SW (G1022/003/01).



Plate 75. Hut 90: E wall before conservation, looking NE
(G1022/003/03).



Plate 76. Huts 89 & 90: internal partition before conservation,
looking SE (G1022/004/02).



Plate 77. Hut 90: entrance from hut 53 before conservation,
looking E (G1022/003/08).



Plate 78. Hut 89: entrance from hut 53 before conservation,
looking N (G1022/004/11).

Plate 79. Hut 90:
entrance from hut 53
in 1956, looking E
(RCAHM 890464/6).



Plate 80. Hut 89:
entrance from hut 53
in 1956, looking N
(RCAHM 890464/8).



Plate 81. Hut 53: inner face
of W wall after removal of
tumble, looking N
(G1022/007/11).



Plate 82. Hut 53: foundations
of W jamb of doorway to hut
89, looking W (G1022/007/15).





Plate 83. Hut 90: base of E wall after removal of collapse,
looking E (G1022/015/33).



Plate 84. Hut 89: base of NE wall after removal of collapse,
looking NE (G1022/015/36).

Plate 85. Hut 89: foundations
of possible cross wall,
looking NW (G1022/016/06A).



Plate 86. Hut 89: restored N
and NE walls, looking NE
(G1022/022/31A).





Plate 87. Hut 90; restored E wall, looking E (G1022/022/33A).



Plate 88. Huts 89 & 90: restored NE wall, looking NE (G1022/022/34A).



Plate 91. Hut 89: general view after conservation, looking W
(G1022/022/32A).



Plate 92. Hut 87: NE wall with experimental capping, looking NW
(G1022/022/08A).



Plate 93. Inner rampart, length D - E, showing changes in construction (G1022/016/23A).



Plate 94. Inner rampart, length D - E, showing changes in construction (G1022/016/31A).



Plate 95. N postern, outer end in 1956, looking SW (RCAHM 890451/6).



Plate 96. N postern, outer end before conservation in 1989, looking S (G1022/008/08A).

Plate 97. N postern,
inner end in 1956,
looking N
(RCAHM 890466/12).



Plate 98. N postern, inner end
before conservation in 1989,
looking N (G1022/008/22A).





Plate 99. N postern and 'ramp': general view before conservation,
looking NE (G1022/008/14A).



Plate 100. N postern: access cleared in front of passage, looking S
(G1022/008/24A).



Plate 101. Parapet to E of N postern, looking E (G1022/009/09A).



Plate 102. N postern: original inner wall face exposed to E of passage, looking E (G1022/010/12).



Plate 103. N postern: E side of passage partly cleared, looking E (G1022/010/10).



Plate 104. N postern: original inner wall face exposed to W of passage, looking N (G1022/023/29).



Plate 105. N postern: the outer lintel before removal (G1022/010/04).



Plate 106. The broken lintel.



Plate 107. N postern: outer E corner of passage
before dismantling, looking SE (G1022/010/06).

Plate 108. N postern: outer
E corner of passage after
dismantling, looking E
(G1022/010/14).



Plate 109. N postern after
conservation, looking S
(G1022/023/27).





Plate 110. N postern: outer W corner before conservation, looking W (G1022/011/15A).



Plate 111. N postern: outer W corner before conservation, looking W (G1022/011/17A).

Plate 112. N postern: E face
of passage during clearance,
looking S (G1022/010/18).



Plate 113. N postern: E side
of passage before dismantling
looking E (G1022/010/11).





Plate 114. N postern: E side of passage after dismantling, with original inner wall face exposed, looking E (G1022/010/20).



Plate 115. N postern: E side of passage after conservation, looking SE (G1022/011/06A).



Plate 116. N postern: W side of passage after conservation, looking N (G1022/011/09A).



Plate 117. N postern, with replacement lintels, looking E (G1022/011/18A).



Plate 118. N postern after re-roofing, looking S (G1022/023/26).



Plate 119. N postern after re-roofing, looking N (G1022/023/28).



Plate 120. Collapse 'N'
before conservation, looking
S (G1022/008/06A).



Plate 121. Collapse 'N' after
clearance of tumble, looking
E (G1022/012/09).



Plate 122. Collapse 'N' after clearance of tumble, looking SW (G1022/012/06).



Plate 123. Collapse 'N': wall being refaced, looking W (G1022/012/12).



Plate 124. Collapse 'N' after conservation, looking S. Scales
set as in Plate 120. (G1022/023/23).



Plate 125. Collapse 'N' after conservation, looking SW (G1022/023/24).



Plate 126. Collapse 'N': top of wall after conservation, with rebuilt parapet, looking W (G1022/023/34).



Plate 127. Collapse 'N': inner face after conservation, looking N (G1022/023/35).



Plate 128. Collapse 'N': inner face after conservation,
looking NW (G1022/023/36).



Plate 129. Collapse 'E1' before conservation, looking NW
(G1022/013/12).



Plate 130. Collapse 'E1'
after removal of tumble,
looking W (G1022/014/18).



Plate 131. Collapse 'E1'
after removal of tumble,
looking SW (G1022/014/20).

Plate 132. Collapse 'E1'
after conservation, looking
SW (G1022/022/23A).



Plate 133. Collapse 'E1'
after conservation, looking
NW (G1022/022/22A).





Plate 134. Outer face of rampart, with collapse 'F1' in centre, before conservation, looking S (G1022/015/13).



Plate 135. Collapse 'F1' after conservation, looking E (G1022/023/14).



Plate 136. Collapse 'F1': top of wall after conservation, looking NE (G1022/023/18).