


TRE'R CEIRI
CONSERVATION PROJECT
1990
PART 2: PLATES



REPORT ON THE SECOND SEASON OF THE
TRE'R CEIRI CONSERVATION PROJECT
JUNE - NOVEMBER 1990

S.D. BOYLE

FOR

GWYNEDD ARCHAEOLOGICAL TRUST LTD.

PART 2: PLATES

List of Plates.

(Archive negative nos. are given at the end of each caption).

1. Collapse I: outer face of the wall.
2. Collapse I: inner face.
3. Hut 77 in 1956.
4. Hut 77 in 1990, with eroded pathway along its SE wall.
5. 'New' summit cairn, August 1990.
6. Hut 2: general view before conservation.
7. Hut 2: top of NW wall, before conservation.
8. Hut 2: NW wall before conservation.
9. Hut 2: NE wall after conservation.
10. Hut 2: NW wall after conservation.
11. Hut 2: top of NW wall after conservation.
12. Hut 78: general view before conservation.
13. Hut 78: general view before conservation.
14. Hut 78: collapsed N corner and hut entrance.
15. Hut 78: N corner before conservation.
16. Hut 78: N corner after removal of rubble.
17. Hut 78: N corner after conservation.
18. Hut 78: SE wall and S corner before conservation.
19. Hut 78: S corner before conservation.
20. Hut 78: S corner after dismantling of modern rebuild.
21. Hut 78: S corner after conservation.
22. Hut 78: NW wall before conservation.
23. Hut 78: NW wall after conservation.
24. Hut 78A: General view, looking NE.
25. Hut 89: Rebuilt door jamb, February 1990.
26. Hut 89: Door jamb collapsed, September 1990.
27. Hut 89: Door jamb replaced, November 1990.
28. Hut 89: partition at rear of hut.
29. Collapse D before conservation.
30. Collapse D before conservation.
31. Collapse D after clearance of tumble/loose masonry.
32. Collapse D after clearance of tumble/loose masonry.
33. Collapse D after conservation.
34. Collapse D after conservation.
35. Wall D-E: outer face before conservation.
36. Wall D-E: blocked entrance.
37. Wall D-E: blocked entrance, showing facing of earlier entrance.
38. Collapse D1 after conservation.
39. Collapse D2 before conservation.
40. Collapse D2 after conservation.
41. Collapse D3 before conservation.
42. Collapse D3 after clearance of tumble/unstable masonry.
43. Collapse D3 after conservation.
44. Collapses D4 & D5 before conservation.
45. Collapse D4 after conservation.
46. Collapse D5 after conservation.
47. Collapse D6 before conservation.
48. Collapse D6 after conservation.
49. Collapse D7 before conservation.
50. Collapse D7 after conservation.

51. Collapse D8 before conservation.
52. Collapses D8 & D9 after conservation.
53. Collapse D9 before conservation.
54. Collapse D10 before conservation.
55. Collapse D10 after clearance of tumble/unstable masonry.
56. Collapse D10 after clearance of tumble/unstable masonry.
57. Collapse D10 after conservation.
58. Collapse D10 after conservation.
59. Collapses D10 & D11 after conservation.
60. Collapse D11 before conservation.
61. Collapse D11 after clearance of tumble.
62. Collapse D11 after conservation.
63. Collapse D11 after conservation.
64. Collapse E before conservation.
65. Collapse E before conservation.
66. Collapse E after clearance of rubble.
67. Collapse E after clearance of rubble.
68. Collapse E after clearance of rubble.
69. Collapse E after conservation.
70. Collapse E after conservation.
71. Collapse E (inner face) before conservation.
72. Collapse E (inner face) after clearance of tumble.
73. Collapse E (inner face) after conservation.
74. Collapse E2 before conservation.
75. Collapse E2 after conservation.
76. Collapse E3 before conservation.
77. Collapse E3 after dismantling: SW facing section.
78. Collapse E3 after conservation.
79. Collapse E3 after conservation.
80. Collapse E4 before conservation.
81. Collapse E4 after conservation.
82. Collapse E5 before conservation.
83. Collapse E5 after conservation.
84. Collapse E6 before conservation.
85. Collapse E6 before conservation.
86. Collapse E6 after clearance of rubble.
87. Collapse E6 after conservation.
88. Collapse E6 after conservation.
89. Collapse F before conservation.
90. Collapse F before conservation.
91. Collapse F: NE edge of collapse before dismantling.
92. Collapse F: SW edge of collapse, before dismantling.
93. Collapse F: SW-facing section during clearance of rubble.
94. Collapse F: SW-facing section after clearance of rubble.
95. Collapse F after clearance of rubble.
96. Collapse F after clearance of rubble.
97. Collapse F: rebuilding outer face.
98. Collapse F after conservation.
99. Collapse F after conservation.
100. Collapse F (inner face) before conservation.
101. Collapse F (inner face) after clearance of rubble.
102. Collapse F (inner face) after conservation.
103. Main Wall F-G: general view before conservation.
104. Collapse F2 before conservation.
105. Collapses F2 & F5 after conservation.

106. Collapse F3 before conservation.
107. Pinning base of wall at F3.
108. Collapse F3 after conservation.
109. Buttress at Collapse F3.
110. Buttress at Collapse F3, looking NE (G1022/117/36).
111. Collapse F4 before conservation.
112. Collapse F4 after conservation.
113. Collapse F5 before conservation.
114. Collapse F6 before conservation.
115. Collapse F6 after conservation.
116. Collapse F7 before conservation.
117. Collapse F7 after clearance of unstable masonry.
118. Collapse F7 after conservation.
119. Wall top behind Hut 77 before conservation.
120. Inner face of main wall at huts 78/78A, before conservation.
121. Collapse H2 after clearance of rubble.
122. Collapse H3 before conservation.
123. Collapse H3 after removal of unstable masonry.
124. Collapses H2, H3 & H4 after conservation.
125. Collapse H3 after conservation.
126. Collapse H4 after clearance of rubble.
127. Collapse H4 after clearance of rubble.
128. Collapse H4: unstable masonry to NE of collapse before dismantling.
129. Collapse H4 after conservation.
130. Wall capping between F1 and F7.
131. Wall capping, wall D-E.



Plate 1. Collapse I: outer face of the wall (G1022/113/06).



Plate 2. Collapse I: inner face (G1022/110/13A).

Plate 3. Hut 77 in 1956, looking N (R.C.A.H.M. 890449/18).



Plate 4. Hut 77 in 1990, with eroded pathway along its SE wall, looking N (G1022/026/16A).



Plate 5. 'New' summit cairn, August 1990 (G1022/115/04).



Plate 6. Hut 2: general view before conservation, looking NE
(G1022/114/15).

Plate 7. Hut 2: top of NW wall, before conservation, looking NE (G1022/114/19).



Plate 8. Hut 2: NW wall before conservation, looking NW (G1022/114/20).





Plate 9. Hut 2: NE wall after conservation, looking NE (G1022/119/21).



Plate 10. Hut 2: NW wall after conservation, looking NW (G1022/119/18).

Plate 11. Hut 2: top of NW wall after conservation, looking NE (G1022/119/22).




Plate 12. Hut 78: general view before conservation, looking W (G1022/109/05).





Plate 13. Hut 78: general view before conservation, looking S
(G1022/109/06).



Plate 14. Hut 78: collapsed N corner and hut entrance, looking NE
(G1022/109/11).



Plate 15. Hut 78: N corner
before conservation, looking N
(G1022/109/12).



Plate 16. Hut 78: N corner
after removal of rubble,
looking NE (G1022/032/24).



Plate 17. Hut 78: N corner after conservation, looking N
(G1022/113/25)



Plate 18. Hut 78: SE wall and S corner before conservation, looking SE
(G1022/109/08).



Plate 19. Hut 78: S corner before conservation, looking S (G1022/109/10).



Plate 20. Hut 78: S corner after dismantling of modern rebuild, looking S (G1022/113/23).



Plate 21. Hut 78: S corner after conservation, looking S
(G1022/119/14).



Plate 22. Hut 78: NW wall before conservation, looking NW
(G1022/107/26).




Plate 23. Hut 78: NW wall after conservation, looking NW
(G1022/119/11).



Plate 24. Hut 78A: General view, looking NE (G1022/113/22).



Plate 25. Hut 89: Rebuilt door jamb (bottom centre of frame),
February 1990, looking W (G1022/022/11A).



Plate 26. Hut 89: Door jamb collapsed, September 1990
(G1022/115/18).



Plate 27. Hut 89: Door jamb replaced, November 1990
(G1022/119/25).



Plate 28. Hut 89: partition at rear of hut, looking E
(G1022/115/19).



Plate 29. Collapse D before conservation, looking SW (G1022/116/15).



Plate 30. Collapse D before conservation, looking E (G1022/116/13).



Plate 31. Collapse D after clearance of
tumble/loose masonry, looking NE
(G1022/116/19).



Plate 32. Collapse D after clearance of
tumble/loose masonry, looking NE
(G1022/116/16).

Plate 33. Collapse D after
conservation, looking SW
(G1022/118/13).



Plate 34. Collapse D after
conservation, looking E
(G1022/118/09).





Plate 35. Wall D-E: outer face before conservation, looking E
(G1022/115/29).



Plate 36. Wall D-E: blocked entrance, looking SE (G1022/15/31).



Plate 37. Wall D-E: blocked entrance, showing
facing of earlier entrance, looking S
(G1022/118/17).

Plate 38. Collapse D1 after
conservation, looking SE
(G1022/118/18).



Plate 39. Collapse D2 before
conservation, looking SE
(G1022/115/34).





Plate 40. Collapse D2 after conservation, looking SE (G1022/118/20).



Plate 41. Collapse D3 before conservation, looking NW (G1022/104/12).



Plate 42. Collapse D3 after clearance of tumble/unstable masonry, looking NW (G1022/115/22).



Plate 43. Collapse D3 after conservation, looking NW (G1022/118/32).



Plate 44. Collapses D4 & D5 before conservation, looking NW. The blocked entrance visible on the outer face would have entered the fort between the two scales. (G1022/104/20).



Plate 45. Collapse D4 after conservation, looking NW (G1022/118/35).



Plate 46. Collapse D5 after
conservation, looking NW
(G1022/118/36).



Plate 47. Collapse D6 before
conservation, looking NW
(G1022/104/21).



Plate 48. Collapse D6 after conservation,
looking NW (G1022/118/34).



Plate 49. Collapse D7 before conservation,
looking SE (G1022/101/10).



Plate 50. Collapse D7 after conservation,
looking SE (G1022/118/19).

Plate 51. Collapse D8 before conservation, looking SE (G1022/101/029).




Plate 52. Collapses D8 & D9 after conservation, looking SE (G1022/118/15).




Plate 53. Collapse D9 before conservation, looking SE (G1022/101/31).




Plate 54. Collapse D10 before conservation, looking NW (G1022/104/11).





Plate 55. Collapse D10 after clearance of
tumble/unstable masonry, looking SW
(G1022/116/22).

Plate 56. Collapse D10 after clearance of tumble/unstable masonry, looking SW (G1022/116/23).



Plate 57. Collapse D10 after conservation, looking NW (G1022/119/03).





Plate 58. Collapse D10 after conservation, looking SW (G1022/117/30).



Plate 59. Collapses D10 & D11 after conservation, looking NW
(G1022/117/32).



Plate 60. Collapse D11 before conservation, looking NW (G1022/104/19).



Plate 61. Collapse D11 after clearance of tumble, looking SW (G1022/116/28).



Plate 62. Collapse D11 after conservation, looking NW (G1022/119/04).



Plate 63. Collapse D11 after conservation, looking N (G1022/119/02).



Plate 64. Collapse E before conservation, looking SE (G1022/115/20).



Plate 65. Collapse E before conservation, looking E (G1022/115/21).



Plate 66. Collapse E after clearance of rubble, looking E
(G1022/116/04).



Plate 67. Collapse E after clearance of rubble, looking SE
(G1022/116/05).

Plate 68. Collapse E after
clearance of rubble, looking
SW (G1022/116/03).



Plate 69. Collapse E after
conservation, looking SE
(G1022/117/07).





Plate 70. Collapse E after conservation, looking E (G1022/117/06).




Plate 71. Collapse E (inner face) before conservation, looking NW (G1022/104/03).

Plate 72. Collapse E (inner face) after clearance of tumble, looking SW (G1022/116/09)



Plate 73. Collapse E (inner face) after conservation, looking NW (G1022/118/31).



Plate 74. Collapse E2 before conservation, looking S (G1022/114/34).



Plate 75. Collapse E2 after conservation, looking SE (G1022/118/26).





Plate 76. Collapse E3 before conservation, looking S (G1022/116/20).



Plate 77. Collapse E3 after dismantling: SW facing section (G1022/116/32).



Plate 78. Collapse E3 after conservation, looking SE (G1022/118/27).



Plate 79. Collapse E3 after conservation, looking S (G1022/118/29).



Plate 80. Collapse E4 before conservation, looking SE (G1022/014/12-13).



Plate 81. Collapse E4 after conservation, looking SE (G1022/118/06).



Plate 82. Collapse E5 before conservation, looking SE (G1022/014/09).



Plate 83. Collapse E5 after conservation,
looking SE (G1022/118/07)

Plate 84. Collapse E6 before conservation, looking NE (G1022/022/24A).



Plate 85. Collapse E6 before conservation, looking NW (G1022/022/22A).





Plate 86. Collapse E6 after clearance of rubble, looking SW (G1022/117/02).



Plate 87. Collapse E6 after conservation, looking NW (G1022/117/15).



Plate 88. Collapse E6 after conservation, looking N (G1022/117/13).



Plate 89. Collapse F before conservation, looking E (G1022/114/21).



Plate 90. Collapse F before conservation, looking SE (G1022/114/22).



Plate 91. Collapse F: NE edge of collapse
before dismantling, looking SE
(G1022/114/23-24).



Plate 92. Collapse F: SW edge of collapse,
before dismantling, looking SE
(G1022/114/25).



Plate 93. Collapse F: SW-facing section during clearance of rubble (G1022/114/27).



Plate 94. Collapse F: SW-facing section after clearance of rubble (G1022/114/32).




Plate 95. Collapse F after clearance of rubble,
showing surviving basal course of wall face,
looking NE (G1022/115/10).

Plate 96. Collapse F after
clearance of rubble, looking
NE (G1022/115/12).




Plate 97. Collapse F:
rebuilding outer face, looking
SW (G1022/115/15).





Plate 98. Collapse F after conservation, looking SE (G1022/118/03).



Plate 99. Collapse F after conservation, looking E (G1022/118/05).



Plate 100. Collapse F (inner face) before conservation, looking NW (G1022/013/09).



Plate 101. Collapse F (inner face) after clearance of rubble, looking SW (G1022/115/13).



Plate 102. Collapse F (inner face) after conservation, looking NW
(G1022/117/11).



Plate 103. Main Wall F-G: general view before conservation, looking SW
(G1022/015/14).



Plate 104. Collapse F2 before conservation,
looking SE (G1022/014/32-33).



Plate 105. Collapses F2 & F5
after conservation, looking SE
(G1022/117/33).



Plate 106. Collapse F3 before
conservation, looking SE
(G1022/014/28).

Plate 107. Pinning base of wall at F3 (G1022/114/14).



Plate 108. Collapse F3 after conservation, looking SE (G1022/117/35).





Plate 109. Buttress at Collapse F3, looking S (G1022/118/01).



Plate 110. Buttress at Collapse F3, looking NE (G1022/117/36).



Plate 111. Collapse F4 before conservation, looking NW
(G1022/013/06-07).



Plate 112. Collapse F4 after conservation, looking NW (G1022/117/09).

Plate 113. Collapse F5 before conservation, looking SE (G1022/014/34).



Plate 114. Collapse F6 before conservation, looking NW (G1022/012/31).





Plate 115. Collapse F6 after conservation, looking NW (G1022/117/08).



Plate 116. Collapse F7 before conservation, looking NW (G1022/012/29).



Plate 117. Collapse F7 after clearance of unstable masonry, looking N (G1022/114/29).



Plate 118. Collapse F7 after conservation, looking W (G1022/114/36).




Plate 119. Wall top behind Hut 77 before conservation, with H1 behind the scale, looking NE (G1022/109/27).



Plate 120. Inner face of main wall at huts 78/78A, before conservation, looking NW (G1022/107/27).




Plate 121. Collapse H2 after clearance of rubble, looking SW
(G1022/113/27).



Plate 122. Collapse H3 before conservation, looking NW
(G1022/107/32).



Plate 123. Collapse H3 after removal of unstable masonry, looking N
(G1022/113/31).



Plate 124. Collapses H2, H3 & H4 after conservation, looking W
(G1022/114/35).



Plate 125. Collapse H3 after conservation, looking NW (G1022/119/06).



Plate 126. Collapse H4 after clearance of rubble, looking W (G1022/114/06).



Plate 127. Collapse H4 after clearance of rubble, looking W
(G1022/114/09).



Plate 128. Collapse H4: unstable masonry to NE of collapse before
dismantling, looking NW (G1022/114/08).



Plate 129. Collapse H4 after conservation, looking NW (G1022/119/05).




Plate 130. Wall capping between F1 and F7, looking NE (G1022/119/23).



Plate 131. Wall capping, wall D-E, looking SW
(G1022/117/31).