

**YMDDIRIEDOLAETH ARCHAEOLEGOL GWYNEDD
GWYNEDD ARCHAEOLOGICAL TRUST**

**REPORT ON THE FOURTH SEASON OF THE
TRE'R CEIRI CONSERVATION PROJECT
JUNE TO NOVEMBER 1992**

PART 2: PLATES

D. HOPEWELL

LIST OF PLATES

- Plate 1, G1022\144\03, Collapse L6, before conservation.
- Plate 2, G1022\155\23, Collapse L6, after conservation.
- Plate 3, G1022\144\04,07, Collapse L7, before conservation.
- Plate 4, G1022\155\29, Collapse L7, after conservation.
- Plate 5, G1022\144\15, Collapse L8, before conservation.
- Plate 6, G1022\155\33, Collapse L8, after conservation.
- Plate 7, G1022\144\29, Collapse L12, before conservation, stones marked.
- Plate 8, G1022\148\01, Collapse L12, after clearance.
- Plate 9, G1022\156\04, Collapse L12, after conservation.
- Plate 10, G1022.0189, Collapse M (North postern), outer.
- Plate 11, G1022\150\35, Helicopter returning lintel.
- Plate 12, G1022.0758, Collapse M, (North postern), outer, during conservation.
- Plate 13, G1022.0056, Collapse M, (North postern), outer, before conservation.
- Plate 14, G1022\156\10, Collapse M, (North postern), outer, after conservation
- Plate 15, G1022\156\05, Collapse M, (North postern), inner, after conservation
- Plate 16, G1022\148\10, Collapse N1 (west), before conservation, showing marked stones.
- Plate 17, G1022\148\11, Collapse N1 (east), before conservation, showing marked stones.
- Plate 18, G1022\149\11, Collapse N1, after clearance.
- Plate 19, G1022\156\12, Collapse N1, after conservation.
- Plate 20, G1022\145\35a, Collapse C, outer face, (north), before conservation.
- Plate 21, G1022\145\36a, Collapse C, outer face, (centre), before conservation.
- Plate 22, G1022\146\03a, Collapse C, outer face, (south), before conservation.
- Plate 23, G1022\147\07, Collapse C, outer face, (south), slipped forward facing.
- Plate 24, G1022\147\08, Collapse C, outer face, after clearance.
- Plate 25, G1022\153\26, Collapse C, outer face, (north), after conservation.
- Plate 26, G1022\153\23, Collapse C, outer face, (centre), after conservation.
- Plate 27, G1022\153\21, Collapse C, outer face, (south), after conservation.

Plate 28, G1022\145\04, Collapse C, inner face before conservation.

Plate 29, G1022\153\08, Collapse C, inner face, after conservation.

Plate 30, G1022\146\06a, Collapse B6 (west postern, outer), before conservation.

Plate 31, G1022\146\31, West postern, passage, before conservation.

Plate 32, G1022\145\09a, Collapse B3 (west postern, inner), before conservation.

Plate 33, G1022\147\27, Collapse B6 (west postern, outer), after clearance.

Plate 34, G1022\147\16, Collapse B3 (west postern, inner), after clearance.

Plate 35, G1022\147\17, Collapse B3 (west postern, inner), after clearance,
showing line of facing.

Plate 36, G1022\147\18, Collapse B3 (west postern, inner), after clearance.

Plate 37, G1022\153\29, Collapse B6 (west postern, outer), after conservation.

Plate 38, G1022\156\14, Collapse B3 (west postern, inner), after conservation.

Plate 39, G1022\146\8a, Collapse B5, before conservation.

Plate 40, G1022\155\13, Collapse B5, after conservation.

Plate 41, G1022\146\12a, Collapse B4, before conservation.

Plate 42, G1022\155\12, Collapse B4, after conservation.

Plate 43, G1022\155\03, Wall B4 to B, after conservation, showing reset stones.

Plate 44, G1022\155\10, Wall B4 to B, after conservation, showing reset stones.

Plate 45, G1022\145\13, Collapse B2, before conservation.

Plate 46, G1022\153\15, Collapse B2, after conservation.

Plate 47, G1022\145\25a, Collapse B1, before conservation.

Plate 48, G1022\145\15a, Collapse B1 (south) showing marked stones.

Plate 49, G1022\147\25, Collapse B1, after clearance.

Plate 50, G1022\153\18, Collapse B1 (north), after conservation.

Plate 51, G1022\153\36, Collapse B1 (south), after conservation.

Plate 52, R.C.A.M.890451\18 S.W. Entrance 1956.

Plate 53, G1022\149\53, S.W. Entrance 1992, before conservation.

Plate 54, G1022\145\29a, Collapse A1, before conservation.

Plate 55, G1022\145\24a, Collapse B, inner face (south), before conservation.

Plate 56, G1022\145\26a, Collapse B, inner face (north), before conservation.

Plate 57, G1022\149\05, Collapse B, inner face after clearance.

Plate 58, G1022\150\09, Collapse A1, after clearance showing marked stones.

Plate 59, G1022\154\07, Collapse B, inner face, (south), after conservation.

Plate 60, G1022\150\04, Collapse B, inner face, (north), after conservation.

Plate 61, G1022\154\08, Collapse A1\B, after conservation.

Plate 62, G1022\146\25a, Collapse B, outer face.

Plate 63, G1022\146\19a, Collapse B, outer face, (north) before conservation,
showing marked stones.

Plate 64, G1022\149\21, Collapse B, outer face, slipped forward face, before conservation.

Plate 65, G1022\146\21a, Collapse B, outer face, (centre), before conservation.

Plate 66, G1022\146\24a, Collapse B, outer face, (south), before conservation.

Plate 67, G1022\146\29a, Collapse B, outer face, (south), before conservation.

Plate 68, G1022\147\32, Collapse B, outer face, after clearance.

Plate 69, G1022\149\27, Collapse B, outer face, after clearance.

Plate 70, G1022.0801, Collapse B, outer face, detail.

Plate 71, G1022\52\05, Collapse B\Bastion, outer face.

Plate 72, G1022.0752, Face hidden behind bastion, after clearance.

Plate 73, G1022\149\25, Collapse B, Lower face, after clearance.

Plate 74, G1022\149\18, Collapse B, slipped forward outer face, after clearance.

Plate 75, G1022\154\34, Collapse B, outer face, after conservation.

Plate 76, G1022\147\34, Collapse B, outer face, showing marked stones.

Plate 77, G1022\147\35, Collapse B, outer face, showing extent of *in situ* masonry.

Plate 78, G1022\154\29, Collapse B, outer face, after conservation.

Plate 79, G1022\150\14, Collapse A3, before conservation.

Plate 80, G1022\154\24, Collapse A3, after conservation.

Plate 81, G1022\151\29, Collapse A3, internal face.

Plate 82, G1022\154\26, Collapse A3, after conservation.

Plate 83, G1022\150\10, Collapse A6, before conservation.

Plate 84, G1022\151\27, Collapse A6, after clearance.

Plate 85, G1022\154\22, Collapse A6, after conservation.

Plate 86, G1022\147\13, Collapse A5 (west), before conservation, showing marked stones.

Plate 87, G1022\149\29, Collapse A5 (east), before conservation, showing marked stones.

Plate 88, G1022\154\17, Collapse A5, after conservation.

Plate 89, G1022\149\31, Collapse A4, before conservation, showing marked stones.

Plate 90, G1022\151\10, Collapse A4, after clearance.

Plate 91, G1022\156\21, Collapse A4, after conservation

Plate 92, G1022\105\33a, Collapse EE1, before conservation.

Plate 93, G1022\151\11, Collapse EE1, before conservation.

Plate 94, G1022\151\13, Collapse EE1, before conservation.

Plate 95, G1022\152\30, Collapse A7, collapse into passage.

Plate 96, G1022\152\36, S.W entrance passage, during clearance.

Plate 97, G1022\152\35, S.W entrance passage, during clearance.

Plate 98, G1022\155\16, Slabs on S.W. entrance passage floor.

Plate 99, G1022\152\31, Collapse A7, during clearance.

Plate 100, G1022\153\33, Collapse A7, after clearance.

Plate 101, G1022\154\13, Collapse A7, after conservation.

Plate 102, G1022\155\22, Collapse EE1 and S.W entrance passage, after conservation

Plate 103, G1022\156\15, Collapse EE1 and S.W entrance passage, after conservation

Plate 104, G1022\154\30, Collapse EE1 and S.W entrance passage, after conservation

Plate 105, G1022\151\15, Collapse EE2, before conservation.

Plate 106, G1022\156\17, Collapse EE2, after conservation.



Plate 1, G1022/144/03, Collapse L6, before conservation



Plate 2, G1022/155/23, Collapse L6, after conservation.



Plate 3, G1022/144/04, 07, Collapse L7, before conservation.



Plate 4, G1022/155/29, Collapse L7, after conservation.



Plate 5, G1022/144/15, Collapse L8, after conservation.



Plate 6, G1022/155/33, Collapse L8, after conservation.



Plate 7, G1011/144/29, Collapse L12, before conservation, stones marked.



Plate 8, G1022/148/01, Collapse L12, after clearance.



Plate 9, G1022/156/04, Collapse L12, after conservation.



Plate 10, G1022.0189, Collapse M (North Postern), outer.



Plate 11, G1022/150/35, Helicopter returning lintel.



Plate 12, G1022.0758, Collapse M, (North Postern), outer during conservation.



Plate 13, G1022.0056, Collapse M, (North Postern), outer before conservation.



Plate 14, G1022/156/10, Collapse M, (North Postern), outer, after conservation.



Plate 15, G1022/156/05, Collapse M, (North Postern), inner, after conservation.



Plate 16, G1022/148/10, Collapse N1 (west), before conservation, showing marked stones.



Plate 17, G1022/148/11, Collapse N1 (east), before conservation, showing marked stones.



Plate 18, G1022/149/11, Collapse N1, after clearance.



Plate 19, G1022/156/12, Collapse N1, after conservation.



Plate 20, G1022/145/35a, Collapse C, outer face, (north), before conservation.



Plate 21, G1022/145/36a, Collapse C, outer face, (centre), before conservation.



Plate 22, G1022/146/03a, Collapse C, outer face, (south), before conservation.



Plate 23, G1022/147/07, Collapse C, outer face, (south), slipped forward facing.



Plate 24, G1022/147/08, Collapse C, outer face, after clearance.



Plate 25, G1022/153/26, Collapse C, outer face, (north), after conservation.



Plate 26, G1022/153/23, Collapse C, outer face, (centre), after conservation.



Plate 27, G1022/153/21, Collapse C, outer face, (south), after conservation.



Plate 28, G1022/145/04, Collapse C, inner face before conservation.



Plate 29, G1022/153/08, Collapse C, inner face, after conservation.



Plate 30, G1022/146/06a, Collapse B6 (west postern, outer), before conservation.



Plate 31, G1022/146/31, West postern, passage, before conservation.



Plate 32, G1022/145/09a, Collapse B3 (west postern, inner), before conservation.



Plate 33, G1022/147/27, Collapse B6 (west postern, outer), after clearance.



Plate 34, G1022/147/16, Collapse B3 (west postern, inner), after clearance.



Plate 35, G1022/147/17, Collapse B3 (west postern, inner), after clearance, showing line of facing.



Plate 36, G1022/147/18, Collapse B3 (west postern, inner), after clearance.



Plate 37, G1022/153/29, Collapse B6 (west postern, outer), after conservation.



Plate 38, G1022/156/14, Collapse B3 (west postern, inner), after conservation.



Plate 39, G1022/146/8a, Collapse B5, before conservation.



Plate 40, G1022/155/13, Collapse B5, after conservation.



Plate 41, G1022/146/12a, Collapse B4, before conservation.



Plate 42, G1022/155/12, Collapse B4, after conservation.



Plate 43, G1022/155/03, Wall B4 to B, after conservation, showing reset stones.



Plate 44, G1022/155/10, Wall B4 to B, after conservation, showing reset stones.



Plate 45, G1022/145/13, Collapse B2, before conservation.



Plate 46, G1022/153/15, Collapse B2, after conservation.



Plate 47, G1022/145/25a, Collapse B1, before conservation.



Plate 48, G1022/145/15a, Collapse B1 (south) showing marked stones.



Plate 49, G1022/147/25, Collapse B1, after clearance.



Plate 50, G1022/153/18, Collapse B1 (north), after conservation.



Plate 51, G1022/153/36, Collapse B1 (south), after conservation.



Plate 52, R.C.A.M. 890451/18 S.W. Entrance 1956.



Plate 53, G1022/149/53, S.W. Entrance 1992, before conservation.



Plate 54, G1022/145/29a, Collapse A1, before conservation.



Plate 55, G1022/145/24a, Collapse B, inner face (south), before conservation.



Plate 56, G1022/145/26a, Collapse B, inner face (north), before conservation.



Plate 57, G1022/149/05, Collapse B, inner face after clearance.



Plate 58, G1022/150/09, Collapse A1, after clearance showing marked stones.



Plate 59, G1022/154/07, Collapse B, inner face (south), after conservation.



Plate 60, G1022/150/04, Collapse B, inner face (north), after conservation.



Plate 61, G1022/154/08, Collapse A1/B, after conservation.



Plate 62, G1022/146/25a, Collapse B, outer face.



Plate 63, G1022/146/19a, Collapse B, outer face, (north) before conservation, showing marked stones.



Plate 64, G1022/149/21, Collapse B, outer face, slipped forward face, before conservation.



Plate 65, G1022/146/21a, Collapse B, outer face, (centre), before conservation.



Plate 66, G1022/146/24a, Collapse B, outer face, (south), before conservation.



Plate 67, G1022/146/29a, Collapse B, outer face, (south), before conservation.



Plate 68, G1022/147/32, Collapse B, outer face, after clearance.



Plate 69, G1022/149/27, Collapse B, outer face, after clearance.



Plate 70, G1022.0801, Collapse B, outer face, detail.



Plate 71, G1022/52/05, Collapse B/Bastion, outer face.



Plate 72, G1022.0753, Face hidden behind bastion, after clearance.



Plate 73, G1022/149/25, Collapse B, Lower face, after clearance.



Plate 74, G1022/149/18, Collapse B, slipped forward outer face, after clearance.



Plate 75, G1022/154/34, Collapse B, outer face, after conservation.



Plate 76, G1022/147/34, Collapse B, outer face, showing marked stones.



Plate 77, G1022/147/35, Collapse B, outer face, showing extent of *in situ* masonry.



Plate 78, G1022/154/29, Collapse B, outer face, after conservation.



Plate 79, G1022/150/14, Collapse A3, before conservation.



Plate 80, G1022/154/24, Collapse A3, after conservation.



Plate 81, G1022/151/29, Collapse A3, internal face.



Plate 82, G1022/154/26, Collapse A3, after conservation.



Plate 83, G1022/150/10, Collapse A6, before conservation.



Plate 84, G1022/151/27, Collapse A6, after clearance.



Plate 85, G1022/154/22, Collapse A6, after conservation.



Plate 86, G1022/147/13, Collapse A5 (west), before conservation, showing marked stones.



Plate 87, G1022/149/29, Collapse A5 (east), before conservation, showing marked stones.



Plate 88, G1022/154/17, Collapse A5, after conservation.



Plate 89, G1022/149/31, Collapse A4, before conservation, showing marked stones.



Plate 90, G1022/151/10, Collapse A4, after clearance.



Plate 91, G1022/156/21, Collapse A4, after conservation.



Plate 92, G1022/105/33a, Collapse EE1, before conservation.



Plate 93, G1022/151/11, Collapse EE1, before conservation.



Plate 94, G1022/151/13, Collapse EE1, before conservation.



Plate 95, G1022/152/30, Collapse A7, collapse into passage.



Plate 96, G1022/152/36, S.W. entrance passage, during clearance.



Plate 97, G1022/152/35, S.W. entrance passage, during clearance.



Plate 98, G1022/155/16, Slabs on S.W. entrance passage floor.



Plate 99, G1022/152/31, Collapse A7, during clearance.



Plate 100, G1022/153/33, Collapse A7, after clearance.



Plate 101, G1022/154/13, Collapse A7, after conservation.



Plate 102, G1022/155/22, Collapse EE1 and S.W. entrance passage, after conservation.



Plate 103, G1022/156/15, Collapse EE1 and S.W. entrance passage, after conservation.



Plate 104, G1022/154/30, Collapse EE1 and S.W. entrance passage, after conservation.



Plate 105, G1022/151/15, Collapse EE2, before conservation.



Plate 106, G1022/156/17, Collapse EE2, after conservation.