

REPORT ON THE FIFTH SEASON OF THE
TRE'R CEIRI CONSERVATION PROJECT
APRIL TO SEPTEMBER 1993

PART 2: PLATES

Ymddiriedolaeth Archaeolegol Gwynedd
Gwynedd Archaeological Trust

PART 2

LIST OF PLATES

- Plate 1 G1022/158/13 ; Collapse F8 before conservation.
Plate 2 G1022/158/16 ; Collapse F8 before conservation.
Plate 3 G1022/158/17 ; Collapse F8 before conservation.
Plate 4 G1022/158/20 ; Collapse F8 before conservation.
Plate 5 G1022/169/02 ; Collapse F8 after conservation.
Plate 6 G1022/169/04 ; Collapse F8 after conservation.
Plate 7 G1022/169/07 ; Collapse F8 after conservation.
Plate 8 G1022/169/10 ; Collapse F8 after conservation.
Plate 9 G1022/161/03 ; Collapse F14 before conservation.
Plate 10 G1022/165/22 ; Collapse F13 abutting the outer face of the rampart.
Plate 11 G1022/170/01 ; Collapses F13 and F14 after conservation.
Plate 12 G1022/159/14 ; Collapse H1 before conservation.
Plate 13 G1022/159/16 ; Collapse H1 before conservation.
Plate 14 G1022/159/18 ; Collapse H1 before conservation.
Plate 15 G1022/164/04 ; Collapse H1 after clearance.
Plate 16 G1022/170/02 ; Collapse H1 after conservation.
Plate 17 G1022/170/04 ; Collapse H1 after conservation.
Plate 18 G1022/159/20 ; Collapse H, inner face before conservation.
Plate 19 G1022/170/06 ; Collapse H, inner face after conservation.
Plate 20 G1022/159/24 ; Collapse G4 before conservation.
Plate 21 G1022/170/14 ; Collapse G4 after conservation.
Plate 22 G1022/160/10 ; Collapse H3 before conservation.
Plate 23 G1022/171/00 ; Collapse H3 after conservation.
Plate 24 G1022/160/12 ; Collapse H13, showing voids in the facing before conservation.
Plate 25 G1022/171/02 ; Collapse H13, showing voids in the facing after conservation.
Plate 26 G1022/160/17 ; Collapse H4 before conservation.
Plate 27 G1022/160/19 ; Collapse H4 before conservation.
Plate 28 G1022/160/21 ; Collapse H4 before conservation.
Plate 29 G1022/171/05 ; Collapse H4 after conservation.
Plate 30 G1022/171/07 ; Collapse H4 after conservation.
Plate 31 G1022/171/09 ; Collapse H4 after conservation.
Plate 32 G1022/160/25 ; Collapse H before conservation.
Plate 33 G1022/160/27 ; Collapse H before conservation.
Plate 34 G1022/163/35 ; Collapse H after clearance.
Plate 35 G1022/164/01 ; Collapse H after clearance.
Plate 36 G1022/164/00 ; Collapse H showing straight joints.
Plate 37 G1022/171/11 ; Collapse H after conservation.
Plate 38 G1022/171/15 ; Collapse H after conservation.
Plate 39 G1022/160/30 ; Collapse G5 before conservation.
Plate 40 G1022/160/31 ; Collapse G5 before conservation.
Plate 41 G1022/166/06 ; Collapse G5 after clearance.
Plate 42 G1022/171/17 ; Collapse G5 after conservation.
Plate 43 G1022/171/20 ; Collapse G5 after conservation.
Plate 44 G1022/159/08 ; N.W. entrance before conservation, outer end.
Plate 45 G1022/159/01 ; N.W. entrance before conservation, outer end.
Plate 46 G1022/158/28 ; N.W. entrance before conservation, inner end.
Plate 47 R.C.A.M. (Wales) 890451/4 ; N.W. entrance in 1956.
Plate 48 G1022/158/24 ; Collapse F9 before conservation.
Plate 49 G1022/158/26 ; Collapse F9 before conservation.
Plate 50 G1022/162/16 ; Collapse F10 before conservation.
Plate 51 G1022/162/18 ; Collapse F10 before conservation.
Plate 52 G1022/162/20 ; Collapse F11 before conservation.
Plate 53 G1022/158/36 ; Collapse F11 before conservation.
Plate 54 G1022/159/03 ; Collapses F11 and F12 before conservation.

Plate 55 G1022/159/04 ; Collapse F12 before conservation.
 Plate 56 G1022/159/07 ; Collapse F12 before conservation.
 Plate 57 G1022/159/30 ; Collapse G1 before conservation.
 Plate 58 G1022/159/31 ; Collapse G1 before conservation.
 Plate 59 G1022/159/33 ; Collapse G1 before conservation.
 Plate 60 G1022/159/36 ; Collapse G2 before conservation.
 Plate 61 G1022/160/05 ; Collapse G3 before conservation.
 Plate 62 G1022/160/08 ; Collapse G before conservation.
 Plate 63 G1022/163/06 ; Step in N.W. passage floor after clearance.
 Plate 64 G1022/163/07 ; Fallen slabs in N.W. passage floor after some clearance.
 Plate 65 G1022/163/11 ; Edge set slabs in N.W. passage floor after some clearance.
 Plate 66 G1022/163/20 ; Rough revetment in front of collapse F11.
 Plate 67 G1022/163/17 ; Rough revetment in front of collapse F11.
 Plate 68 G1022/163/27 ; Section through the rubble in the outer end of the N.W. entrance.
 Plate 69 G1022/164/10 ; N.W. passage floor after clearance.
 Plate 70 G1022/164/16 ; Collapse F11 after clearance of the passage.
 Plate 71 G1022/164/14 ; Collapse F11 after clearance of the passage.
 Plate 72 G1022/164/12 ; Collapse F11 after clearance of the passage.
 Plate 73 G1022/1047 ; Collapse F11 after clearance.
 Plate 74 G1022/164/25 ; Collapse F11 after clearance showing the 'hidden face'.
 Plate 75 G1022/164/20 ; Roman pottery in collapse F11.
 Plate 76 G1022/169/26 ; Collapse F11 after conservation.
 Plate 77 G1022/169/29 ; Collapse F11 after conservation.
 Plate 78 G1022/1059 ; Collapse F10 after clearance of the passage.
 Plate 79 G1022/1072 ; Cordoned off N.W. passage.
 Plate 80 G1022/1063 ; Collapse F10 showing tilted stones 5 and 3.
 Plate 81 G1022/164/36 ; Collapse F10 after further clearance.
 Plate 82 G1022/165/13 ; Collapse F10 basal course.
 Plate 83 G1022/165/12 ; Collapse F10 basal course showing relationship to outer face of rampart
 Plate 84 G1022/165/16 ; Base of F10 after removal of stones 1 and 2.
 Plate 85 G1022/169/20 ; Collapse F10 after conservation.
 Plate 86 G1022/169/24 ; Collapse F10 after conservation.
 Plate 87 G1022/169/22 ; Collapse F10 after conservation.
 Plate 88 G1022/169/16 ; Collapse F9 after conservation.
 Plate 89 G1022/169/19 ; Collapse F9 after conservation.
 Plate 90 G1022/163/26 ; Collapse F12 after clearance of stone from the passage.
 Plate 91 G1022/165/35 ; Collapse F12 after clearance.
 Plate 92 G1022/169/32 ; Collapse F12 after conservation.
 Plate 93 G1022/169/34 ; Collapse F12 after conservation
 Plate 94 G1022/163/09 ; Collapse G1 after clearance of passage.
 Plate 95 G1022/163/13 ; Collapse G1, collapse behind stone P.
 Plate 96 G1022/165/36 ; Collapse G1, after clearance of stone P.
 Plate 97 G1022/170/23 ; Collapse G1, N.W. end, after conservation.
 Plate 98 G1022/166/16 ; Collapse G1, S.E. end, after clearance.
 Plate 99 G1022/166/08 ; Collapse G1, S.E. end, after clearance.
 Plate 100 G1022/170/21 ; Collapse G1 after conservation.
 Plate 101 G1022/170/25 ; Collapses G2 and G3 after conservation.
 Plate 102 G1022/170/30 ; Collapse G after conservation.
 Plate 103 G1022/167/26 ; Collapse G1 showing slabs at base of wall.
 Plate 104 G1022/170/31 ; Collapse G after conservation.
 Plate 105 G1022/165/30 ; Stony layer in passage floor.
 Plate 106 G1022/170/35 ; Passage floor after conservation.
 Plate 107 G1022/1143 ; N.W. entrance after conservation.
 Plate 108 G1022/166/30 ; Collapse GG before conservation.
 Plate 109 G1022/166/33 ; Collapse GG before conservation.
 Plate 110 G1022/167/36 ; Collapse GG after clearance.
 Plate 111 G1022/167/33 ; Collapse GG after clearance.
 Plate 112 G1022/167/31 ; Collapse GG showing semi-collapsed earlier facing.

Plate 113 G1022/173/12 ; Collapse GG after conservation.
 Plate 114 G1022/173/08 ; Collapse GG after conservation.
 Plate 115 G1022/166/22 ; Collapse HH1 before conservation.
 Plate 116 G1022/173/07 ; Collapse HH1 after conservation.
 Plate 117 G1022/168/17 ; Lower banquette before conservation.
 Plate 118 G1022/171/26 ; Lower banquette (W) after conservation.
 Plate 119 G1022/171/28 ; Lower banquette (E) after conservation.
 Plate 120 G1022/168/26 ; Collapse N2 before conservation.
 Plate 121 G1022/173/15 ; Collapse N2 after conservation.
 Plate 122 G1022/161/10 ; Collapse N3 before conservation.
 Plate 123 G1022/171/31 ; Collapse N3 after conservation.
 Plate 124 G1022/161/17 ; Collapse N4 before conservation.
 Plate 125 G1022/171/34 ; Collapse N4 after conservation.
 Plate 126 G1022/172/18 ; Collapse N4 (inner face) after conservation.
 Plate 127 G1022/157/08 ; Collapses N5 and N6 before conservation.
 Plate 128 G1022/172/23 ; Collapses N5 and N6 after conservation.
 Plate 129 G1022/157/13 ; Collapses N8 and N10 before conservation.
 Plate 130 G1022/172/26 ; Collapses N8 and N10 after conservation.
 Plate 131 G1022/157/18 ; Collapse N11 before conservation.
 Plate 132 G1022/172/30 ; Collapse N11 after conservation.
 Plate 133 G1022/157/20 ; Collapse N12 before conservation.
 Plate 134 G1022/172/31 ; Collapse N12 after conservation.
 Plate 135 G1022/161/24 ; Voids N13, N14 and N15 before conservation.
 Plate 136 G1022/171/36 ; Voids N13 and N14 after conservation.
 Plate 137 G1022/172/01 ; Void N15 after conservation.
 Plate 138 G1022/161/29 ; Collapse N16 and void N17 before conservation.
 Plate 139 G1022/172/02 ; Collapse N16 and void N17 before conservation.
 Plate 140 G1022/161/34 ; Collapse N18 before conservation.
 Plate 141 G1022/172/04 ; Collapse N18 after conservation.
 Plate 142 G1022/162/04 ; Collapse N19 before conservation.
 Plate 143 G1022/162/02 ; Collapse N19 before conservation.
 Plate 144 G1022/161/35 ; Collapse N19 before conservation.
 Plate 145 G1022/172/10 ; Collapse N19 after conservation.
 Plate 146 G1022/172/08 ; Collapse N19 after conservation.
 Plate 147 G1022/172/06 ; Collapse N19 after conservation.
 Plate 148 G1022/162/11 ; Collapse N20 before conservation.
 Plate 149 G1022/162/09 ; Collapse N20 before conservation.
 Plate 150 G1022/172/17 ; Collapse N20 after conservation.
 Plate 151 G1022/172/12 ; Collapse N20 after conservation.
 Plate 152 G1022/151/19 ; Collapse EE before conservation.
 Plate 153 G1022/151/30 ; Collapse EE before conservation.
 Plate 154 G1022/151/33 ; Collapse DD1 before conservation.
 Plate 155 G1022/168/01 ; Collapse EE after clearance.
 Plate 156 G1022/172/33 ; Collapse EE after conservation.
 Plate 157 G1022/172/35 ; Collapses EE and DD after conservation.
 Plate 158 G1022/168/07 ; Collapse DD after clearance.
 Plate 159 G1022/1151 ; Tre'r Ceiri from the N.W. showing the conserved ramparts.




Plate 1 G1022/158/13 ; Collapse F8 before conservation.



Plate 2 G1022/158/16 ; Collapse F8 before conservation.



Plate 3 G1022/158/17 ; Collapse F8 before conservation.




Plate 4 G1022/158/20 ; Collapse F8 before conservation.



Plate 5 G1022/169/02 ; Collapse F8 after conservation.



Plate 6 G1022/169/04 ; Collapse F8 after conservation.



Plate 7 G1022/169/07 ; Collapse F8 after conservation.



Plate 8 G1022/169/10 ; Collapse F8 after conservation.



Plate 9 G1022/161/03 ; Collapse F14 before conservation.



Plate 10 G1022/165/22 ; Collapse F13 abutting the outer face of the rampart.



Plate 11 G1022/170/01 ; Collapses F13 and F14 after conservation.



Plate 12 G1022/159/14 ; Collapse H1 before conservation.



Plate 13 G1022/159/16 ; Collapse H1 before conservation.




Plate 14 G1022/159/18 ; Collapse H1 before conservation.



Plate 15 G1022/164/04 ; Collapse H1 after clearance.



Plate 16 G1022/170/02 ; Collapse H1 after conservation.



Plate 17 G1022/170/04 ; Collapse H1 after conservation.



Plate 18 G1022/159/20 ; Collapse H, inner face before conservation.



Plate 19 G1022/170/06 ; Collapse H, inner face after conservation.



Plate 20 G1022/159/24 ; Collapse G4 before conservation.



Plate 21 G1022/170/14 ; Collapse G4 after conservation.




Plate 22 G1022/160/10 ; Collapse H3 before conservation.



Plate 23 G1022/171/00 ; Collapse H3 after conservation.



Plate 24 G1022/160/12 ; Collapse H13, showing voids in the facing before conservation.



Plate 25 G1022/171/02 ; Collapse H13, showing voids in the facing after conservation.




Plate 26 G1022/160/17 ; Collapse H4 before conservation.




Plate 27 G1022/160/19 ; Collapse H4 before conservation.




Plate 28 G1022/160/21 ; Collapse H4 before conservation.



Plate 29 G1022/171/05 ; Collapse H4 after conservation.



Plate 30 G1022/171/07 ; Collapse H4 after conservation.



Plate 31 G1022/171/09 ; Collapse H4 after conservation.




Plate 32 G1022/160/25 ; Collapse H before conservation.




Plate 33 G1022/160/27 ; Collapse H before conservation.



Plate 34 G1022/163/35 ; Collapse H after clearance.



Plate 35 G1022/164/01 ;
Collapse H after clearance.




Plate 36 G1022/164/00 ;
Collapse H showing straight joints.



Plate 37 G1022/171/11 ; Collapse H after conservation.



Plate 38 G1022/171/15 ; Collapse H after conservation.




Plate 39 G1022/160/30 ; Collapse G5 before conservation.



Plate 40 G1022/160/31 ; Collapse G5 before conservation.



Plate 41 G1022/166/06 ; Collapse G5 after clearance.



Plate 42 G1022/171/17 ; Collapse G5 after conservation.



Plate 43 G1022/171/20 ; Collapse G5 after conservation.



Plate 44 G1022/159/08 ; N.W. entrance before conservation, outer end.



Plate 45 G1022/159/01 ; N.W. entrance before conservation, outer end.



Plate 46 G1022/158/28 ; N.W. entrance before conservation, inner end.



Plate 47 R.C.A.M. (Wales) 890451/4 ; N.W. entrance in 1956.



Plate 48 G1022/158/24 ; Collapse F9 before conservation.



Plate 49 G1022/158/26 ; Collapse F9 before conservation.



Plate 50 G1022/162/16 ; Collapse F10 before conservation.



Plate 51 G1022/162/18 ; Collapse F10 before conservation.



Plate 52 G1022/162/20 ; Collapse F11 before conservation.



Plate 53 G1022/158/36 ; Collapse F11 before conservation.




Plate 54 G1022/159/03 ; Collapses F11 and F12 before conservation.




Plate 55 G1022/159/04 ; Collapse F12 before conservation.




Plate 56 G1022/159/07 ; Collapse F12 before conservation.



Plate 57 G1022/159/30 ; Collapse G1 before conservation.



Plate 58 G1022/159/31 ; Collapse G1 before conservation.




Plate 59 G1022/159/33 ; Collapse G1 before conservation.



Plate 60 G1022/159/36 ; Collapse G2 before conservation.



Plate 61 G1022/160/05 ; Collapse G3 before conservation.



Plate 62 G1022/160/08 ; Collapse G before conservation.



Plate 63 G1022/163/06 ; Step in N.W. passage floor after clearance.



Plate 64 G1022/163/07 ; Fallen slabs in N.W. passage floor after some clearance.



Plate 65 G1022/163/11 ; Edge set slabs in N.W. passage floor after some clearance.



Plate 66 G1022/163/20 ; Rough revetment in front of collapse F11.



Plate 67 G1022/163/17 ; Rough revetment in front of collapse F11.



Plate 68 G1022/163/27 ; Section through the rubble in the outer end of the N.W. entrance.



Plate 69 G1022/164/10 ; N.W. passage floor after clearance.



Plate 70 G1022/164/16 ; Collapse F11 after clearance of the passage.



Plate 71 G1022/164/14 ; Collapse F11 after clearance of the passage.



Plate 72 G1022/164/12 ; Collapse F11 after clearance of the passage.



Plate 73 G1022/1047 ; Collapse F11 after clearance.



Plate 74 G1022/164/25 ; Collapse F11 after clearance showing the 'hidden face.'



Plate 75 G1022/164/20 ; Roman pottery in collapse F11.



Plate 76 G1022/169/26 ; Collapse F11 after conservation.



Plate 77 G1022/169/29 ; Collapse F11 after conservation.



Plate 78 G1022/1059 ; Collapse F10 after clearance of the passage.



Plate 79 G1022/1072 ;
Cordoned off N.W. passage.



Plate 80 G1022/1063 ;
Collapse F10 showing tilted stones 5 and 3.



Plate 81 G1022/164/36 ; Collapse F10 after further clearance.



Plate 82 G1022/165/13 ; Collapse F10 basal course.



Plate 83 G1022/165/12 ; Collapse F10 basal course showing relationship to outer face of rampart.



Plate 84 G1022/165/16 ; Base of F10 after removal of stones 1 and 2.



Plate 85 G1022/169/20 ; Collapse F10 after conservation.



Plate 86 G1022/169/24 ; Collapse F10 after conservation.



Plate 87 G1022/169/22 ; Collapse F10 after conservation.



Plate 88 G1022/169/16 ; Collapse F9 after conservation.



Plate 89 G1022/169/19 ; Collapse F9 after conservation.



Plate 90 G1022/163/26 ; Collapse F12 after clearance of stone from the passage.



Plate 91 G1022/165/35 ; Collapse F12 after clearance.



Plate 92 G1022/169/32 ; Collapse F12 after conservation.



Plate 93 G1022/169/34 ; Collapse F12 after conservation



Plate 94 G1022/163/09 ; Collapse G1 after clearance of passage.



Plate 95 G1022/163/13 ; Collapse G1, collapse behind stone P.



Plate 96 G1022/165/36 ; Collapse G1, after clearance of stone P.



Plate 97 G1022/170/23 ; Collapse G1, N.W. end, after conservation.



Plate 98 G1022/166/16 ; Collapse G1, S.E. end, after clearance.



Plate 99 G1022/166/08 ; Collapse G1, S.E. end, after clearance.



Plate 100 G1022/170/21 ; Collapse G1 after conservation.



Plate 101 G1022/170/25 ; Collapses G2 and G3 after conservation.



Plate 102 G1022/170/30 ; Collapse G after conservation.



Plate 103 G1022/167/26 ; Collapse G1 showing slabs at base of wall.



Plate 104 G1022/170/31 ; Collapse G after conservation.



Plate 105 G1022/165/30 ; Stony layer in passage floor.



Plate 106 G1022/170/35 ; Passage floor after conservation.



Plate 107 G1022/1143 ; N.W. entrance after conservation.



Plate 108 G1022/166/30 ; Collapse GG before conservation.



Plate 109 G1022/166/33 ; Collapse GG before conservation.



Plate 110 G1022/167/36 ; Collapse GG after clearance.



Plate 111 G1022/167/33 ; Collapse GG after clearance.



Plate 112 G1022/167/31 ; Collapse GG showing semi-collapsed earlier facing.



Plate 113 G1022/173/12 ; Collapse GG after conservation.



Plate 114 G1022/173/08 ; Collapse GG after conservation.



Plate 115 G1022/166/22 ; Collapse HH1 before conservation.



Plate 116 G1022/173/07 ; Collapse HH1 after conservation.



Plate 117 G1022/168/17 ; Lower banquette before conservation.



Plate 118 G1022/171/26 ; Lower banquette (W) after conservation.



Plate 119 G1022/171/28 ; Lower banquette (E) after conservation.



Plate 120 G1022/168/26 ; Collapse N2 before conservation.



Plate 121 G1022/173/15 ; Collapse N2 after conservation.




Plate 122 G1022/161/10 ; Collapse N3 before conservation.



Plate 123 G1022/171/31 ; Collapse N3 after conservation.




Plate 124 G1022/161/17 ; Collapse N4 before conservation.



Plate 125 G1022/171/34 ; Collapse N4 after conservation.



Plate 126 G1022/172/18 ; Collapse N4 (inner face) after conservation.




Plate 127 G1022/157/08 ; Collapses N5 and N6 before conservation.



Plate 128 G1022/172/23 ; Collapses N5 and N6 after conservation.




Plate 129 G1022/157/13 ; Collapses N8 and N10 before conservation.



Plate 130 G1022/172/26 ; Collapses N8 and N10 after conservation.




Plate 131 G1022/157/18 ; Collapse N11 before conservation.



Plate 132 G1022/172/30 ; Collapse N11 after conservation.




Plate 133 G1022/157/20 ; Collapse N12 before conservation.



Plate 134 G1022/172/31 ; Collapse N12 after conservation.



Plate 135 G1022/161/24 ; Voids N13, N14 and N15 before conservation.



Plate 136 G1022/171/36 ; Voids N13 and N14 after conservation.



Plate 137 G1022/172/01 ; Void N15 after conservation.



Plate 138 G1022/161/29 ; Collapse N16 and void N17 before conservation.



Plate 139 G1022/172/02 ; Collapse N16 and void N17 before conservation.



Plate 140 G1022/161/34 ; Collapse N18 before conservation.



Plate 141 G1022/172/04 ; Collapse N18 after conservation.




Plate 142 G1022/162/04 ; Collapse N19 before conservation.



Plate 143 G1022/162/02 ; Collapse N19 before conservation.




Plate 144 G1022/161/35 ; Collapse N19 before conservation.



Plate 145 G1022/172/10 ; Collapse N19 after conservation.



Plate 146 G1022/172/08 ; Collapse N19 after conservation.



Plate 147 G1022/172/06 ; Collapse N19 after conservation.




Plate 148 G1022/162/11 ; Collapse N20 before conservation.




Plate 149 G1022/162/09 ; Collapse N20 before conservation.



Plate 150 G1022/172/17 ; Collapse N20 after conservation.



Plate 151 G1022/172/12 ; Collapse N20 after conservation.



Plate 152 G1022/151/19 ; Collapse EE before conservation.




Plate 153 G1022/151/30 ; Collapse EE before conservation.



Plate 154 G1022/151/33 ; Collapse DD1 before conservation.



Plate 155 G1022/168/01 ; Collapse EE after clearance.



Plate 156 G1022/172/33 ; Collapse EE after conservation.



Plate 159 G1022/1151 ; Tre'r Ceiri from the N.W. showing the conserved ramparts.